

Crystal Clean Case Study # 1

Address: 1720 West Mulberry St., Suite B-1, Fort Collins, CO 80521

Report Date: June 20, 2006

Pre Test Results

<u>Sample No.</u>	<u>Area Sampled</u>	<u>Analysis</u>	<u>Methods</u>	<u>Result</u>	<u>Units</u>
06130500-01	Main Floor	Meth	GC/MS	<0.02	µg/100cm ²
06130500-02	Stairwell	Meth	GC/MS	0.67	µg/100cm ²
06130500-03	Basement Kitchen	Meth	GC/MS	32.22	µg/100cm ²
06130500-04	Basement Apt.	Meth	GC/MS	<0.02	µg/100cm ²
06130500-05	Basement HVAC	Meth	GC/MS	3.82	µg/100cm ²
06130500-06	Field Blank	Meth	GC/MS	<0.02	µg/100cm ²

<0.02=Non-Detected

Post Test Results

<u>Sample No.</u>	<u>Area Sampled</u>	<u>Analysis</u>	<u>Method</u>	<u>Result</u>	<u>Units</u>
072505JD-01	100cm ²	Meth	GC/MS	<0.02	µg/100cm ²
072505JD-02	100cm ²	Meth	GC/MS	<0.02	µg/100cm ²
072505JD-03	200cm ²	Meth	GC/MS	<0.02	µg/100cm ²
072505JD-04	200cm ²	Meth	GC/MS	<0.02	µg/100cm ²
072505JD-05	200cm ²	Meth	GC/MS	<0.02	µg/100cm ²
072505JD-06	100cm ²	Meth	GC/MS	<0.02	µg/100cm ²

<0.02=Non-Detected

Lab Results Provided By:

Morse Environmental, Inc.
PO Box 1557
Auburn, WA 98071

&

Legacy Laboratory Services
1225 NE 2nd Ave.
Portland, OR 97232

