

## Crystal Clean Case Study # 2

Address: 9942 N Sunview Lane, Hayden, ID 83835

Report Date: May 11, 2006

### Pre Test Results

<u>Sample No.</u>	<u>Area Sampled</u>	<u>Analysis</u>	<u>Methods</u>	<u>Result</u>	<u>Units</u>	<u>Result</u>	<u>Units</u>
1718-1	Front Bedroom	Meth	GC/MS	5.29	µg/100cm <sup>2</sup>	21.15	µg/400cm <sup>2</sup>
1718-2	Kitchen / Living Room	Meth	GC/MS	1.64	µg/100cm <sup>2</sup>	6.57	µg/400cm <sup>2</sup>
1718-3	Back Bedroom	Meth	GC/MS	2.67	µg/100cm <sup>2</sup>	10.66	µg/400cm <sup>2</sup>
1718-4	Method Blank	Meth	GC/MS	<0.02	µg/100cm <sup>2</sup>	<0.08	µg/400cm <sup>2</sup>

### Post Test Results

<u>Sample No.</u>	<u>Area Sampled</u>	<u>Analysis</u>	<u>Method</u>	<u>Result</u>	<u>Units</u>
1718-5	Bed 1	Meth	GC/MS	<0.02	µg/100cm <sup>2</sup>
1718-6	Bath 1	Meth	GC/MS	<0.02	µg/100cm <sup>2</sup>
1718-7	Bed 2	Meth	GC/MS	<0.02	µg/100cm <sup>2</sup>
1718-8	Living Room	Meth	GC/MS	<0.02	µg/100cm <sup>2</sup>
1718-9	Kitchen	Meth	GC/MS	<0.02	µg/100cm <sup>2</sup>
1718-10	Bath 2	Meth	GC/MS	<0.02	µg/100cm <sup>2</sup>
1718-11	Bed 3	Meth	GC/MS	<0.02	µg/100cm <sup>2</sup>
1718-12	Method Blank	Meth	GC/MS	<0.02	µg/100cm <sup>2</sup>

Lab Results Provided By:

Morse Environmental, Inc.  
PO Box 1557  
Auburn, WA 98071

&

Legacy Laboratory Services  
1225 NE 2nd Ave.  
Portland, OR 97232

